


# City of Toledo

## Backflow Prevention Assembly Test and Maintenance Report



### Customer Information

Customer / Property Name: **Cedar Creek Church**  
Contact Name: **N/A**  
Property Address: **6950 Whitehouse Square Blvd  
Sylvania, OH 43571**

### Assembly Information

Type: **DC** Model #: **W432100**  
Size: **1/2"** Serial#: **552996**  
Manufacturer: **Apollo** Hazard: **Fire Protection**  
Location:

# PASS

Test Date: 2016-05-05

### Assembly Test Information

Initial Test	
Check Valve #1 1.2 (X) Closed Tight/Held ( ) Leaked	Check Valve #2 1.2 (X) Closed Tight/Held ( ) Leaked
Final Test	
Check Valve #1 1.2 (X) Closed Tight/Held ( ) Leaked	Check Valve #2 1.2 (X) Closed Tight/Held ( ) Leaked

As the tester of record, I affirm this test as: Passed  Failed  **Repairs Made: No**

Additional comments or repairs made / materials (parts) used:

**( no comments )**

### Tester Information

Tester Name: **Trent, Jerold**  
Tester License Expiration: **04-19-2019**  
Certification#: **6351**  
Test Kit Serial #: **625734**  
Test Kit Date Tested for Accuracy: **03-15-2016**  
Test Kit Mfr. & Mod. #: **Watts TK9A**  
Testing Co Name: **ACCEL Fire Systems, Inc.**  
Phone: **(419) 843-7756**  
Address: **3365 Silica Road  
Sylvania, OH 43560**

\*\*The above tester certifies that all information submitted for this report is true and accurate